# ATTACHMENT J.4.6 FINAL HAZARD ANALYSIS REPORT FOR OPERABLE UNIT 4 25-HS-0004, SEPTEMBER 1995

# FINAL HAZARD ANALYSIS REPORT FOR OPERABLE UNIT 4

### 25-HS-0004

Prepared by the FHAR Team Consisting of
Robert Purcell, Chair, FERMCO Safety Analysis
William Tope, FERMCO CRU4 FSAR Coordinator
David Gooderum, FERMCO CRU4 Startup & Operations
Gregg Johnson, FERMCO Health and Safety
Victoria Werner, FERMCO Human Factors Safety
John Bootle, PARSONS Engineering
Mike Chrostowski, PARSONS Environmental Safety and Health

September 1995

# Approval Page

# FINAL HAZARD ANALYSIS FOR OPERABLE UNIT 4

Passel	9/5/95
R. A. Purcell, Chair, PERMCO Safety Analysis	Date
James W. Smith	9/12/95
J. M. Smith, Manager, FERMCO Safety Analysis	Date
M. C. Skriba, Manager, FERMCO CRU4	120195
M. C. Skriba, Manager, FERMCO CRU4	Date

# Final Hazard Analysis Report for Operable Unit 4

# **CONTENTS**

SECT	ION		PAGE
1.0	Execu	tive Summary	1-1
2.0	Introd	luction To Final Hazard Analysis	2-1
	2.1	Criteria	2-1
3.0	Hazar	d Analysis Process	3-1
	3.1	Reactive Materials	3-1
	3.2	Reactive Material Binary Matrix	3-1
	3.3	Facility/Activity Hazard Identification	3-2
	3.4	Facility Activity Hazard Evaluation	3-4
4.0	Identi	fied Safety-Significant Hazards	4-1
5.0	Refere	ences	5-1
APPE	NDICE	s	
Α	OU4 I	ntegrated Hazards Analysis Evaluation	A-1
TABL	ES and	FIGURES	
Table	ES-1	Hazards and Mitigators	1-2
Table	1	Criteria for Safety Significance	2-2
Table	2	Consequence Classification	2-3
Table	3	Reactive Material Binary Matrix	3-5
Table	4	Hazard Type and Criteria for the Hazard Type	3-7
Table	5	OU4 Hazard/Activity Matrix	3-9
Table	6	Identified Hazards and Mitigators	4-1
Figure	e 1	Pilot Plant Process Block Flow Diagram	3-8

### **SECTION 1**

### **EXECUTIVE SUMMARY**

The Final Hazard Analysis on this project was performed to identify standard hazards, safety-significant items, and risks requiring additional analysis. The Final Hazard Analysis uses a process that demonstrates that all Phase II project phases and processes have been analyzed for this identification. The methodology and findings are included in this report, the Final Hazard Analysis Report for OU4.

The result of this analysis is the identification of six safety-significant hazards. Moreover, engineered controls and administrative controls are identified that are used to mitigate these hazards. These requirements are being addressed prior to operation of Operable Unit 4 (OU4) and shall be included in the project Final Safety Analysis Report (FSAR) for OU4. The identified hazards together with the engineered and administrative controls are:

- 1) Explosion in the Furnace
- 2) External Radiation from Process Vessels
- 3) External Dose Hazard from the Vitrified Product
- 4) Personnel Falling into a Silo
- 5) Silo Containment Breached
- 6) Leak/Spill of Molten Glass or Heavy Metals from Furnace

The engineered and administrative controls required to mitigate the hazards are:

- 1) Emergency off-gas rupture disk
- 2) Shielding
- 3) Containment box under melter
- 4) Radiation Protection Program
- 5) Hazardous Material Protection Program
- 6) Silo Dome Load Limits
- 7) Rigging Plan
- 8) Fall Protection Program

Table ES-1 links the mitigators to the hazard. The purpose of the engineered and administrative controls is to mitigate the hazard risk either by reducing the consequence or the probability of occurrence. Each of these hazards and safety-significant controls and mitigators is fully discussed in the FSAR.

1-1 Rev. No.: 0

Table ES-1 - Hazards and Mitigators

Hazard Description	Hazard Type	Engineered Controls	Administrative Controls
Explosion in the Furnace	1	Emergency off- gas rupture disk	None
External radiation from Process Vessels	4	Shielding	Radiation Protection Program
External dose hazard from the vitrified product	4	Shielding	Radiation Protection Program
Personnel falling into a silo	4	None	Radiation Protection Program Hazardous Material Protection Program Silo Dome Load Limits Fall Protection Program
Silo Containment Breached	10	None	Silo Dome Load Limits Rigging Plan
Leak/Spill of Molten Glass or Heavy Metals from Furnace	10	Containment box under melter	None

Key for Hazard Types as Defined in Table ES-1

- 1 Fire/Explosion
- 4 Radioactive
- 10 Spill/Loss of Containment

1-2 Rev. No.: 0

### **SECTION 2**

### INTRODUCTION TO FINAL HAZARD ANALYSIS

As defined in the Integrated Hazard Analysis Plan that was transmitted to DOE (Reference 1), the purpose of the Final Hazards Analysis is to conduct follow-up, systematic hazard and qualitative accident analysis based on the results of the Preliminary Integrated Hazard Analysis for the CRU4 Pilot Plant (PHA) report (Reference 2) to ensure that the final design, construction, and operations incorporate appropriate protection for the general population, co-located workers, and facility workers (operators). This Final Hazards Analysis Report (FHAR) provides the hazard analysis required by DOE Order 5480.23 (Reference 3) for the facility Final Safety Analysis Report (FSAR). Follow-up actions identified in the PHA, such as performing a more detailed analysis or gathering more information where needed, have been incorporated. The scope of this FHAR includes the K-65 Silo 2, Silo 3, and Radon Treatment System (RTS) as they will exist during Phase II pilot plant operations. It also includes Phase II pilot plant operations.

Facilities such as the CRU4 Pilot Plant at this FSAR phase are in construction. Life cycles include project stages from Site Preparation, Construction, Operation, Maintenance/Surveillance, and Decommissioning and Decontamination (D&D).

### 2.1 Criteria

Criteria used in this analysis are:

- Table 1 provides a risk matrix that defines safety significance. The criteria are consistent with DOE STD-3009-94 and recognize the importance of worker safety. The DOE Standard defines the matrix cells as "bins." Anticipated scenarios that result in multiple serious injuries to workers, as well as unlikely scenarios that result in worker fatalities, are considered safety significant.
- 2. Table 2 initially defines consequence class based on the defined consequences to specific populations. Table 2 was generated by the original PHA team to provide boundaries for specification of consequence classification and subsequently revised during further development of safety documents related to this project.
- Standard or common industrial hazards identified in the hazard analysis are not subject to frequency/consequence binning. Standard or industrial hazards are those which are controlled or mitigated by application of OSHA standards.

2-1 Rev. No.: 0

Table 1 - Criteria for Safety Significance

			Hazard Consequence								
Estimated Annual Probability of Occurrence (p)		Low	Moderate	High							
Anticipated	$p \geq 10^{\circ2}$	4	7	9							
Unlikely	$10^{-2} \ge p > 10^{-4}$	2	5	8							
Extremely Unlikely	$10^4 \ge p > 10^6$	1	3	6							
Incredible	10 <sup>-6</sup> ≥ p										

<sup>-</sup> The areas bounded by the dark line indicate areas with safety significance.

2-2 Rev. No.: 0

<sup>-</sup> Binning (Numbers 1 through 9) is based on DOE-STD-3009-94.

Table 2 - Consequence Classification

	Worker Safety	Worker Radiation Exposure	Worker Chemical Exposure	Public Radiation Exposure	Public Chemical Exposure	Public Safety
High	Multiple Fatalities	> 250 Rem	ERPG-3	> 25 Rem	ERGP-2	Serious Injury
Moderate	1 Fatality or >5 Serious Injuries	> 5 but < 250 Rem	ERPG-2	> 0.5 but < 25 Rem	ERPG-1	Minor Injury
Low	> 1 but < 5 Serious Injuries	>0.5 but < 5 Rem	ERPG-1	> 0.01 but < 0.5 Rem	TLV-TWA	No Impact
Below Concern	Minor Injuries	<0.5 Rem	PEL-TWA	< 0.01 Rem and other legal limits on normal emissions	EPA and other legal limits on normal emissions	No Impact

NOTE: For the purposes of this chart a serious injury is defined as an injury that results in a worker being unable to continue his/her work on a normal basis (lost time).

2-3 Rev. No.: 0

### **SECTION 3**

### HAZARD ANALYSIS PROCESS

The team conducted the updated FHAR using a two-step process: 1) identification and 2) analysis.

The process started by listing the materials encountered in the OU4 operation. The material listing included the physical and chemical properties of these materials (Section 3.1). The team then performed an analysis of binary mixtures of the materials (Section 3.2 and Table 3).

A listing of the hazards that are encountered in any generalized process is proposed in Table 4. The team used available information on the existing OU4 facilities and vitrification processes to determine (Section 3.3) when the generalized hazards are encountered. A hazard matrix was prepared to link a potential hazard to a facility/activity (Table 5).

Finally, the identified hazards in Table 5 were sorted by hazard type and entered into an FHAR evaluation Table (Appendix A) along with possible causes and potential unmitigated consequences. After standard industrial hazards were screened out, the remaining hazards were assigned a frequency and consequence class, and the controls and mitigators for each hazard were identified. This information was then used to identify safety-significant design features that require special attention and/or additional analysis. The "Activity Numbers Associated with the Hazard" field of Appendix A provides a cross-reference to the specific hazard evaluated with a facility or activity as identified in Table 5.

### 3.1 Reactive Materials

The materials/compounds/mixtures used in OU4 operations are existing mixtures of compounds (silo contents, production residues), glass-making additives, cooling water, process additives, and effluent treatment chemicals.

# 3.2 Reactive Material Binary Matrix

The chemical and physical consequence of mixing any of these materials/compounds/mixtures is presented in Table 3, Reactive Material Binary Matrix. Special binary reactive hazards identified in this analysis are steam explosions when the hot glass traps small amounts of water or aqueous solutions, charcoal filter fires, and potential for burns/scalds if water is added to strong caustic (instead of the reverse). Table 3 does not address the probability of mixing occurring. The probability of the mixing and any controls/mitigators is evaluated in Appendix A.

3-1 Rev. No.: 0

### 3.3 Facility/Activity Hazard Identification

This analysis technique compares a facility or activity to a list of hazards. The product of this analysis is a matrix indicating the presence of hazards in a facility or activity. Matrix details are dependent on both the data available in the hazards listing and the facility/activity knowledge.

### 3.3.1 Hazards Listing

The generalized hazards for the existing OU4 facilities and operations are identified in Table 4. This list of hazard types was extracted from <u>Guidelines for Hazard Evaluation Procedures</u> (Reference 4). Each hazard is approached by considering whether this hazard can be encountered in an activity, a process step, and/or a facility. Where possible, it is denoted whether the hazard is acute or chronic.

### 3.3.2 Definition of Process, Facility, or Operation Stage

Life Cycle stages are Site Preparation, Construction, Operation, Maintenance/Surveillance, and Shutdown/Decommissioning and Demolition (D&D). Another Life Cycle stage in existing OU4 facilities is their present condition during OU4 vitrification pilot plant operation.

### 3.3.2.1 Pilot Plant

### 3.3.2.1.1 Pilot Plant Life Cycle (Excluding Operations)

Excluding operations, the Vitrification Pilot Plant Life Cycle activities are Site Preparation, Facility Construction, Silo 3 Preparation, Silo 2 Preparation, D&D, and Maintenance (Table 5, Activity Nos. 1 to 6).

### 3.3.2.1.2 Pilot Plant Operations

Vitrification Pilot Plant operations are based on the Process Block Flow Diagram (Figure 1):

Unit Operation	/Activity #
Silo 2 Hydraulic Material Removal	7 - 11
Silo 3 Pneumatic Material Removal	12 - 14
On-Site Transportation of Material	15 - 17
Silo 3 Material Transfer System	18
Slurry Tank	19

3-2 Rev. No.: 0

Unit Operation	/Activity #
Additives	20
Furnace	21
Product Forming	22
Product Handling	23
Furnace Area Storage	24 - 25
Off-Gas Treatment	26 - 32
Emergency Off-Gas	41 - 43
Recycle Water	45 - 48
Radon Sparging	49 - 51
Building Sump	52 - 53
Electrode Cooling Water	54 - 55
Process Cooling Water	56 - 58
Process Air	59 - 60
Standby Power	61 - 64
Sampling and Analysis	65 - 66

# 3.3.2.2 Existing OU4 Facility and Operation

The existing facilities associated with OU4 operations are the K-65 Silos, Silo 3, and the RTS. During the OU4 Phase II operation, the existing facility activity is the operation of the refurbished RTS. The activities are as follows:

Unit Operation	Activity
K-65 Silos	33
Silo 3	34
Existing RTS	35
Existing RTS Operation	36-40

3-3 Rev. No.: 0

# 3.4 Facility/Activity Hazard Evaluation

An evaluation is performed on any potential hazard identified in Section 3.3 (Facility/Activity Hazard Identification). The identified hazards consider the specific hazards identified in Section 3.1 (Reactive Materials) and Section 3.2 (Reactive Material Binary Matrix). Appendix A lists the results of the hazard evaluation.

3-4 Rev. No.: 0

Table 3 - Reactive Material Binary Matrix

1.	K-65 Residue	Mixture of metal oxides, many radioactive, and wet clays and silts.  Layer of fine clay silt (bentonite) added in 1991 to the top of the silo residues to slow radon gas diffusion from radium decay in the residue. The residue is a stratified muck covered with a crusty surface. The bentonite is a foot thick (minimum) slurry seal that lies on top of the crust.										
2.	Silo 3 Residue	Calcined oxides of processed uranium ore. Physical properties of materials are dry and are fine particles with an angle of repose of 20 degrees. Consists of oxides and salts of process wastes containing radioactive material, and is not a major source of radon gas.										
3.	Water	Fluid used as solvent, cooling medium, and for hydraulic mining of the K-65 Silos.										
4.	Air	Working medium in the pneumatic removal from Silo 3 materials, operating slurry and water pumps.										
5.	Flocculent	A material that accelerates slurry settling. This material is organic with minor effects on skin upon direct contact.										
6.	Glass formers	Mixtures of light metal oxides added to the slurry; serves as a flux.  Assists in dissolution of solids.										
7.	Activated Charcoal	Off-gas system adsorbent for radon. Radon-trapping properties poisoned by organics and water. Organics may be combustible.										
8.	Caustic	Used as off-gas chemical scrubbing agent. Material is hazardous.			С							
9.	CaCl <sub>2</sub>	Desiccant, used in the off-gas system (protects activated charcoal from moisture).										
10.	Glass Melt	A mixture of silo residues and glass formers in the molten state (thermal hazards, melt temp > 1100 °F).			A				В	A		
			1.	2.	3.	4.	5.	6.	7.	8.	9.	10.

Table 3 - Binary Reactive Material Matrix (Continued)

React	ive Matrix	
Codes	i	
Α.	Steam	Mixture of glass melt and water or caustic/SDCD. Energetic consequence. Very hazardous local event.
	Explosion	
В.	Charcoal Filter Fire	Glass melt ignites charcoal in charcoal traps. Radioactive material release
C.	Burns/Scalds	Adding small amounts of water to strong caustic or CaCl <sub>2</sub> (instead of the reverse). Local hazard
Note:	This table does	not address the probability of an event occurring. Contact between Silo 3 materials and air is removal process operation.

3-6 Rev. No.: 0

Table 4 - Hazard Type and Criteria for the Hazard Type

Hazard	Warran Trans	
Type #	Hazard Type	Criteria
1.	Fire/Explosion	Does the process/component present a fire/explosion hazard? (Acute Hazard)
2.	Caustic/Acidic	Does the process/component involve a caustic/acidic material? (Acute Hazard)
3.	Toxic	Does the process/component involve a toxic material? (Acute and/or Chronic Hazard)
4.	Radioactive	Does the process/component involve a radioactive material? (Chronic Hazard)
5.	Kinetic/Rotational	Does the process/component involve rotary or linear movement? (Acute Hazard)
6.	Potential/Elevation	Is the process/component elevated, or does it have suspended overhead components? (Acute Hazard)
7.	Electrical	Does the process/component use exposed electrical components? (Acute Hazard)
8.	Thermal/Freezing	Does the process/component involve high/low temperature? (Acute Hazard)
9.	Pressurized Fluids	Does the process/component involve the use of pressurized fluids? (Acute Hazard)
10.	Spill/Loss of Containment	Will breach of the process/component release contained hazardous materials? (Acute and/or Chronic Hazard)
11.	Confined Space	Does the process/component require entry into confined spaces? (Acute Hazard)
12.	Construction Safety	Does construction/maintenance of the process/component involve special hazards?
13.	Industrial Hygiene/Safety	Does the process/component present special Hygiene/Safety Hazards?
14.	Criticality	Does the process/component require special restrictions to reduce the nuclear criticality hazard?
15.	Other	Any additional process/component hazards (i.e. biohazards [BH], external events[EE])?

3-7 Rev. No.: 0

PRIMAR VASTE FLOW PATH

FURNACE OFF-CAS AND TANK WON

NOTE: THIS DIAGRAM SHOWS PROCESS RELATED SYSTEMS ONLY.

Rev. No.: 0

Table 5 - OU4 Hazard/Activity Matrix

									Hazaı	d Ty	e Nu	nber				<u></u>	
Unit Operation	No.	Activity	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Life Cycle of the Pilot Plant (excluding	1	Site Preparation	х			X		Х	X				Х	X	N,H		ВН
	2	Vitrification Facility Construction	Х		Х		Х	Х	Х		х		х	х	N		вн
operation)	3	Silo 3 Preparation (including connect piping)			X	х		х				х		Х	N,H		вн
	4	K-65 Silo Preparation (including connect pump piping)	Х		х	X		Х				х		X	N,H		вн
	5	D&D	Х		x	х		х	х			х	х	Х	N,H, L		ВН
	6	Maintenance	Х	Х	х	х	х	х	х	Т	Х	х	Х	X	N,H, L		ВН
Hydraulic Mining from K-65 Silo	7	Deleted During Review															
	8	Hydraulic Mining Operation			х	X	Х	Х	Х		X	Х			N,H		
	9	Thickener and Flocculent Operations			Х	Х	Х	х	Х	F	Х	Х					EE
	10	Use of Recycle Water During Mining			X	X				F	X	X					
	11	Repair of Bentonite after in situ Operation			Х	Х		Х				Х			N,H		
Pneumatic Removal	12	Deleted During Review														-	
from Silo 3	13	Pneumatic Removal Operation			Х	Х	X	X	X			X					
	14	Filter/ Receiver Operation			X	X	X		X			X					
On-Site	15	Disconnect from Silo 3			X	X		X				X					
Transportation of Material	16	Material Movement to Pilot Plant	Х		X	X	X					x					EE
	17	Transfer to Surge Bin			Х	Х	х	Х				х					

Table 5 - Pilot Plant Matrix (Continued)

									Hazaı	d Ty	e Nu	mber					
Unit Operation	No.	Activity	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Silo 3 Material Transfer	18	Silo 3 Material Feed to Slurry Tank			X	Х	X	X				Х					EE
Slurry Tank	19	Slurry Tank Operations			Х	X				F		Х				5 5	EE
Additives	20	Glass Making Additive Operations			X		Х	1									
Furnace	21a	Level Control	X		X	х						Х			H,L		
	21b	Temperature Control	Х		Х	Х				Т					H,L		
	21c	Pressure Control	Х		Х	х									H,L		
	21d	Electrode Replacement	X		Х	Х		Х	Х	Т		Х			N,H, L		
	21e	Bottom Drain	Х		х	х				Т		Х			XN,H ,L		
	21f	Side Chamber Feed			Х	х		х		Т		Х			N,H, L		
Product Forming	22a	Product Forming (Gob Cutter)			Х	X	X	Х	Х	Т		Х			N,H, L		
Product Handling	23a	Product Cooling/Transport Conveyor	X		Х	Х	X	Х		Т		Х		:	N,H, L		
	23ъ	Loadout Stations			х	X	Х			Т		Х			N,H, L		

Table 5 - Pilot Plant Matrix (Continued)

									Hazar	d Ty	е Мш	nber					
Unit Operation	No.	Activity.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	24	Product Storage in Furnace Area			х	Х				Т		Х			N,H, L		EE
Furnace Area Storage	25	Prep for On-Site Shipping			х	Х	х		,			х					EE
Pilot Plant Off-Gas	26	Quench Tower Operation (Air side)				Х				Т		Т			N,H		
System	27	Scrubber Operation (Air side)			Х	X						X			N,H		
	28	Desiccant Tower Operation			X	Х		X				X			N		
	29	Charcoal Bed Operation	X		X	X						X			N,L		
	30	HEPA Filter Operation	Х			Х						Х			N,L		
	31	Off-Gas Fan/Blower Operation					X								N,L		
	32	Exhaust Stack						X									!
Existing Facilities	33	K-65 Silos			X	Х		X				х					EE
	34	Silo 3			X	X		X				X					EE
	35	Existing RTS System	X		X	X						X					
Existing Facility	36	Deleted During Review															
Operation	37	RTS Piping to/from Silo				Х						Х					
	38	RTS Fan Operation				Х	Х					Х					
	39	RTS Desiccant Tower Operation			Х	Х						X			_		
	40	RTS Charcoal Bed Operation	х		х	Х						Х				·	
Emergency	41	Automatic Valve Operation			х	х						Х			N		
Off-Gas	42	HEPA Filter Operation	Х		х	Х									N,H		
	43	Blower Operation					Х		х						N,H		

3-11 Rev. No.: 0

Table 5 - Pilot Plant Matrix (Continued)

			1						Hazar	d Ty	pe Nu	mber					
Unit Operation	No.	Activity	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	44	Rupture Disk Operation			Х	X						Х					
Recycle Water	45	Recycle Water Tank			X	X				F		Х			N		EE
	46	Recycle Water Pump Operation (and Piping)			Х	х	Х			F	Х	Х		-	N		
	47	Quench Tower Pump Operation (and Piping)			х	х	х			F	х	х			N		
	48a	Cooling Water Heat Exchanger (Recycle Water Side)			х	х				F	X	х			N		
	48b	Waste Fillers			Х	Х				F	х	Х			N		<u> </u>
Radon Removal	49	Sparge Tank			Х	X				F		х			Х		EE
	50	Sparge Tank Pump Operation (and Piping)			х	х				F	х	х			Х		
	51	Electric Immersion Heater Operations	X		Х	Х				Т		Х			Х		

Table 5 - Pilot Plant Matrix (Continued)

<del></del>							•		Hazar	d Ty	e Nu	nber					
Unit Operation	No.	Activity	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Building Sump	52	Building Sump			Х	X				F		X					EE
	53	Building Sump Pump Operation (and Piping)	:		Х	х				F	Х				N		
Electrode Cooling Water	54	Cooling Water Pump Operation (and Piping and Tank)									X				N		:
	55	Radiator Operation					X		X	T	X		·		N,H		
Process Cooling Water	56	Cooling Tower Operation		X			Х				X				N		
	57	Cooling Tower Pump Operation (and Piping)				-					х	-			N		
	58	Heat Exchanger (Cooling Water Side)									X				N		
Process Air	59	Air Compressor Operation						X		Т	X				N,H		
	60	Air Receiving Tank									X						
Standby Power	61	Diesel Engine Operation	X	Х			X			Т	X				N,H		
	62	Generator Operation	Х				X		X						N,H		
	63	Uninterruptible Power Supply (UPS)	х	х					х	Т					N,H, L		
	64	Day Tank (Diesel Fuel No. 2)	X		х						X	X			N,L		
Sampling and	65	Sampling Operation		х	х	х		х		Т	X	Х					
Analysis	66	Analysis In On-site Lab		х	Х	х				T		Х					
Notes	Т - Т	Thermal, F - Freezing, N - Noise, H - He	at Stre	ss, L -	Poor	Lighti	ng, BI	I - Bi	ohazar	rd, EE	- Ext	ernal l	Event				

Rev. No.: 0 3-13

### **SECTION 4**

### IDENTIFIED SAFETY-SIGNIFICANT HAZARDS

The following hazards, as found by the three screening processes (Tables 3, 4, and 5) evaluated in the FHAR (Appendix A), were found to have unmitigated frequency and consequences to meet the criteria for safety significance per Table 1. These hazards and their controls (administrative and engineered) are listed in Table 6. Each of these hazards and safety-significant controls and mitigators is fully discussed in the FSAR.

Table 6 Identified Hazards and Mitigators

Hazard Description	Hazard Type	Engineered Controls	Administrative Controls
Explosion in the Furnace	1	Emergency off- gas rupture disk	None
External radiation from Process Vessels	4	Shielding	Radiation Protection Program
External dose hazard from the vitrified product	4	Shielding	Radiation Protection Program
Personnel falling into a silo	4	None	Radiation Protection Program Hazardous Material Protection Program Silo Dome Load Limits Fall Protection Program
Silo Containment Breached	10	None	Silo Dome Load Limits Rigging Plan
Leak/Spill of Molten Glass or Heavy Metals from Furnace	10	Containment box under melter	None

Key for Hazard Types as Defined in Table 6

- 1 Fire/Explosion
- 4 Radioactive
- 10 Spill/Loss of Containment


4-1 Rev. No.: 0

# **SECTION 5**

### REFERENCES

- Letter, "Integrated Hazard Analysis Plan for the OU4 Pilot Plant," C:CRU4:94-0484, Wilf S. Pickles, FERMCO to Randi B. Allen, DOE-FN, dated August 2, 1994
- 2. Preliminary Integrated Hazard Analysis for the CRU4 Pilot Plant, July 20, 1994
- 3. DOE Order 5480.23, "Nuclear safety Analysis Reports," April 1992
- Guidelines for Hazard Evaluation Procedures, 2nd Edition with Worked Examples, c1992, AIChE,
   TP155.5.G77

5-1 Rev. No.: 0



# **OU4 Integrated Hazard Analysis Evaluation**

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 1 Hazard Description: Activities Associate						
Personnel injury/death due to explosion  Equipment damage  Project delay			N/A	A) Explosive/flammable gas present in area of welding operations     B) Leak of explosive/flammable gas from welding equipment	1. FERMCO Hot Work Permit 2. Air Monitoring for explosive gasses. 3. Certified/experienced welders 4. Fire watch 5. Proper extinguishing agents present in immediate work area.	Standard Hazard
Hazard Type: 1 Hazard Description: Activities Associate	•					
Possible serious personnel injury/death			N/A	A) Spill during local refueling with sparking     B) Spill of stored fuels with sparking	Project operations require minimal flammable material     Task-specific procedures are approved and procedure training completed prior to work.	Standard Hazard
Possible equipment damage				C) Vehicle Fire D) Motor Fire	A fire protection program is in place prior to work initiation	
Loss of material and equipment Local fire				<i>D</i> , 2000 110	<ol> <li>Design includes a fire protection system including portable fire extinguishers and fire hydrants on either side of the plant.</li> </ol>	
					3. The FEMP 24-hour Emergency Response Team (ERT) is trained on the project requirements and the project requirements sent to the Emergency Preparedness Team prior to work initiation  4. Task-specific procedures are approved and procedure training completed prior to work.	
Hazard Type: 1 Hazard Description: Activities* Associate						
None	Moderate	Incredible	0	Buildup of H <sub>2</sub> gas as a result of water decomposition and ignition by lightning or ungrounded equipment	Not a credible scenario since the hydrogen content of the silo gas has been measured at less than 0.1 percent which is less than the Lower Explosive Limit of $H_2$ of 4 percent.	

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 1 Hazard Description: Activities* Associate						
Fire and rupture of the canisters causes large radon and radon daughter release		Unlikely	2	A) Electrical initiator     B) Organics buildup in charcoal	A fire protection program is in place.	
Hazard Type: I Hazard Description: Activities Associate						
Glass lava spills out of furnace causing schedule delay Failure of adjacent	Moderate	Unlikely	5	A) Overpressurization due to steam buildup     (exceeding off-gas system design basis)	1. Design includes engineered overpressurization protection	WSS HAZOP of furnace and emergency off-gas systems was
equipment, piping, or support structure  Possible				B) Operator error due to lack of training	Task-specific procedures are approved and procedure training completed prior to work with furnace.	performed to analyze and specify SSC's for these systems
death/serious injury to on-site personnel						
Spread of contamination						
Hazard Type: 1 Hazard Description: Activities Associate			PA Filter	s Catch Fire Due to Excessive Temperature		
Fire and rupture of the canisters causes large radon release		Unlikely	2	A) Off-gas temperature which enters the charcoal canisters or HEPA filters is above the ignition temperature of the charcoal due to quench tower failure (350-450 degrees C)		

A-2 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bio	Cause	Controls/Mitigators	Comment
Hazard Type: 2 Hazard Description: Activities Associate		: 6, 56, 61, 63,	, 65, 66			
Chemical Burns	Low	Unlikely	2	Exposure during startup and maintenance	Hazardous chemical work permits are issued     Emergency Showers are available prior to start of work     Task-specific procedures are approved and procedure training completed prior to work.	
Hazard Type: 3 Hazard Description: Activities Associate	-					
Possible serious personnel injury/death			N/A	A) Painting	General Work Permits are issued     Hazardous Chemical Work Permits are issued     Proper ventilation equipment are provided, if needed     FERMCO reviews of MSDS for used materials     Respirator is used, if required by MSDS     Respirator training and fit test (including annual refresher)	Standard Hazard
Hazard Type: 3 Hazard Description: Activities Associate	•		ent, CaC	կ, glass making additives, and bentonite		
Personnel inhalation of suspensions	Below Concern	Anticipated	0	Standard pouring, dumping, shredding, and size reduction.	All listed materials have a low toxicity     Hazardous Chemical Work Permits are issued	

A-3 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 3 Hazard Description: Activities Associate	•		26, 30, :	31, 32, 37, 38, 43, and 54 through 63	,	
Reportable personal contamination event	Below Concern	Unlikely	0	A) Operations	Process vessels and piping provide containment of toxic materials.     Off-gas system maintains air leakage into the furnace from the Furnace Room.	
				B) Spills/Leaks C) Loss of furnace off-gas	Design includes secondary container     Design includes emergency off-gas system	
Hazard Type: 4 Hazard Description: Activities Associate			tion Zon	e, which is also a controlled area, without minimum	m requirements	
Possible serious personnel injury/death	Moderate	Extremely Unlikely	3	A) Inadequate personnel protective equipment     B) Human error in following procedures     C) Training inadequate	1. Requirements for hard hat, safety glasses with rigid side shield, steel-toed shoes 2. Construction rules/regulations, GET & refresher training (all personnel, supervisors have OSHA 500 training) 3. All personnel who are to perform work in the construction zone are orientated to the:  a. CRU4 General H&SP b. Job hazard analysis c. SPR awareness d. Health and Safety Requirements Matrix e. General Work Permit requirements	

A-4 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 4 Hazard Description: Activities Associate				rea minimum requirements		
Reportable personal contamination event with potential for increased radiation	Low	Unlikely	2	A) Human error in following procedures     B) Training inadequate	Site Worker and Refresher Training     Site Specific Orientation Training     Minimum Rad I Training     Visitors are escorted by personnel with proper training     Personnel, equipment and material monitoring are required to exit the controlled area	
exposure to the contaminated worker			:	C) Inadequate personnel protective equipment	Requirements for dosimeter (TLD)     Requirements for safety glasses with rigid side shields     Initial FERMCO or approved physical     Initial, annual and termination - In Vivo Testing	4
Hazard Type: 4 Hazard Description: Activities Associate	•		t Releas	ed to the Air from Preparation Activities		
Personnel exposure to contaminated dust	Low	Unlikely	2	A) Excavation and handling of contaminated soil	Design includes an dust suppression system     Radiation Work Permit are issued to ensure proper use of personal protective equipment (PPE) to prevent personnel contamination and exposure     Supervisor ensures prior process knowledge is used to identify potential hot spots	
				on skin, personal, or company issued "clean" cloth 32, 43, 52, and 54 through 66	ing	
Reportable personal contamination event with potential for increased radiation exposure to the contaminated worker	Low	Unlikely	2	A) Improper use of anti-Cs for intended scope of work     B) In plan for radiological work task.     C) Anti-C failure	1. Proper work planning that identifies the intended scope of work.  2. Issuance of FERMCO Radiation Work Permit identifies proper anti-C requirements for intended scope of work.  3. Pre-job brief with workers on work permit that ensures worker understanding of permit requirements for intended scope of work.	

A-5 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 4 Hazard Description: Activities Associate				er from Silo Material during Removal , 17, 18		
Potential to exceed site dose limits resulting in facility shutdown, personnel injury	Below Concern	Anticipated	0	A) Inhalation /ingestion of radionuclide bearing dust residues if silo material exposed to atmosphere	Bag-in/bag-out procedures are in place.     Radiation Work Permit are issued to ensure proper usage of PPE     Task-specific procedures are approved and procedure training completed prior to work.     Design includes contaminated dust control during removal of Silo 3 material	
				B) Radiation Work Permit (RWP) is not updated as work progresses to reflect new conditions		
Hazard Type: 4 Hazard Description Activities Associate		•		ker from Silo Material during Removal 15, 17, 33, 34		•
Potential to exceed site dose limits resulting in facility shutdown, personnel injury	Below Concern	Anticipated	0	A) Presence of higher-than-expected penetrating radiation     B) High level of radon, radium daughter, or thorium products in K-65 material leading to greater than anticipated dose rates	Design applies As Low As Reasonably Achievable     (ALARA) principles     Radiation Work Permit are issued to ensure proper usage     of PPE	
				C) Radon daughters build up in head space of silo higher than expected	Radon Treatment System available, if necessary, to reduce radon concentration in the silo headspace to allow personnel access to the silo dome	
				D) Failure of protective clothing leads to excessive skin dose due to in training	Task-specific (including emergency) procedures are approved and procedure training completed prior to work.     Radiation Work Permit issued to ensure proper usage of PPE	
				E) RWP is not updated as work progresses to reflect new conditions		

A-6 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Commen
				ontaminated Dust, K-65 Decant Sump Liquid, or Ra 15, 18, 19, 21, 29, 33, 37	don in Excess of Allowed Limits	
Adverse environmental impact or release exceeding standard	Below Concern	Anticipated	0	A) Work in the area disturbs excessive amounts of contaminated material     B) Excavation of contaminated soil     C) Handling of contaminated soil	Design includes contaminated dust control     RWP is issued for working in potentially contaminated soil. RWP updated as work progresses to identify contamination areas	
				D) Failure of radon collection systems	Design includes stack effluent monitoring system for radon     Sampling of radon sparge tank prior to release building sump is performed     Maintenance and inspection of filtration equipment is performed per vendor requirements	
				E) The decent tank overflows	During site material removal, operations will monitor and drain the decant tank, as necessary	
Hazard Type: 4 Hazard Description: Activities* Associate External and possible internal contamination	-		3, 15 5	A) Human error while repositioning the removal equipment and associated supports      B) Excessive loads on the dome cause collapse.	Design for silo material removal includes minimal access to the silo dome     Task-specific procedures are approved and procedure training completed prior to work.	WSS Structural Dome Limit

A-7 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause		Controls/Mitigators	Comment
Possible exposure to personnel Monetary loss	Below Concern	Anticipated	0	A) Contamination through routine use     B) Personnel contamination transfers to equipment     C) Material handling accident transfers contamination to equipment	1. 2. 3. 4.	Procedures are in place to minimize the transfer of contamination to equipment decontamination procedures are in place prior to work initiation  Facility Owner shall ensure that bag-in/bag-out procedures are properly applied  Successful completion of training and qualification on material handling and decontamination procedures are completed prior to work	

A-8 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 4 Hazard Description Activities' Associate	: External Radiations and with the Hazard	on from Process 1: 9, 18, 19, 21	Vessels , 29, 33	and Piping , 65		-
Exceeding Personnel Dose Limits	Low	Anticipated	4	A) Contact dose rates in excess of 500 mrem/hr (unshielded) from K-65 material expected	VPP Shielding designed to maintain dose rates below 2 mrem/hr in intermittent use areas and 0.25 mrem/hr in continuous use areas.     Radiation Work Permit issued to ensure proper usage of PPE	wss
				B) Higher than expected radium source term from K-65 residues	Source term used in shielding based on 95th confidence limit on mean of samples taken from silos.	
				C) Process related abnormal operations leads to greater than expected quantities of K-65 material in process vessels	Design applies As Low As Reasonably Achievable     (ALARA) principles. Shielding estimated assuming     process vessels were completely full of K-65 material at 55     percent solids in thickener, 80 percent solids in slurry     tanks, and 100 percent solids in furnace.	
Hazard Type: 4 Hazard Description Activities Associate Exceeding Personnel Dose Limits		n from Sample	s   0	A) Samples contain radium-bearing materials	Radiation work permit issued to ensure proper usage of PPE     Fume Hood Operation (for potential radon concerns)	
Hazard Type: 4 Hazard Description Activities: 45, 46, 4		n from Radon-	Laden W	ater		
Exceeding Personnel Dose Limits	Below Concern	Anticipated	0	A) Concentrations may reach 1.2E8 pCi/l of radon in recycle water	Radiation Work Permit issued to ensure proper usage of PPE     Tanks and sump are vented to off-gas system to eliminate radon buildup in headspace	Thickener is largest source of radon in recycle water system
Hazard Type: 4 Hazard Description: Activities: 39, 40	External Radiatio	n from RTS Pr	ocess Ve	essel		
Exceeding Personnel Dose Limits	Low	Unlikely	2	A) Radon buildup on tower and beds during operation of RTS	Tower and beds are shielded     RTS buildup is in remote location with respect to VPP     Radiation Work Permit issued to ensure proper usage of PPE	

A-9 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 4 Hazard Description: Activities Associate	External Dose Hard with the Hazard	azard from the :: 22, 23, 24, 2	vitrified S	product		
Difficulty in handling material causes schedule delay  Possible exposure to personnel	Low	Anticipated	4	A) Contact dose rates in excess of 500 mrem/hr (unshielded) from K-65 material	ALARA principles are followed and a Radiation Work     Permit issued to ensure proper usage of PPE     Gem Transfer containers designed with shielding to reduce contact dose rate below 50 mrem/hour.	WSS
Hazard Type: 4 Hazard Description: Activities' Associate						<u></u>
Difficulty in storage and handling of the glass causes schedule delay	Low	Unlikely	2	A) Failure of the glass matrix to contain radon	Supervisor will ensure that radon flux is measured and surface contamination is checked prior to transport to the interim storage facility	
Possible exposure to personnel						
Hazard Type: 4 Hazard Description: Activities Associate			vessels	and Piping		
Internal exposure hazard to personnel working in the area	Below Concern	Anticipated	0	A) High radium content in the process material	Design includes process vessel headspace vents to the off- gas system	
				B) Loss of off-gas system	Design includes high airborne contamination alarms near thickener, slurry tanks, and carbon beds     Thickener, slurry tanks, and carbon beds are isolated by shielding from workers during operation	

A-10 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Commen
Hazard Type: 4 Hazard Description: Activities Associate	~		e			
Internal exposure hazard to personnel working in the area	Below Concern	Anticipated	0	A) Loss of off-gas system	Design includes emergency off-gas system for pressure control     Design includes airborne contamination alarms near furnace     Evacuation procedures are approved and procedure training completed prior to working near furnace	
	d with the Hazard	: 2, 6, 8, 9, 13		, 18, 19, 20, 22, 23, 25, 31, 38, 43, 56, 61, 62		
Possible personnel injury/death	Moderate	Extremely Unlikely	3	A) Human Error	Task-specific procedures are approved and procedure training completed prior to work.	
				B) Inappropriate Safety Devices	Project Engineer shall assure that all safety devices are properly installed	
Hazard Type: 6 Hazard Description Activities' Associate						
Possible serious personnel injury/death			N/A	A) Human error in following procedures     B) Training inadequate     C) Inadequate personnel protective equipment	Competent operator (certification per specifications)     General work permit issued to ensure use of proper PPE	Standard Hazard
Hazard Type: 6 Hazard Description Activities* Associate	: Falls from elevated with the Hazard	ed surfaces I: 1, 2, 3, 4, 5,	6, 8, 9,	11, 13, 14, 15, 18, 19, 21d, 21f, 22, 28, 32, 33,	34	
Possible serious personnel injury/death			N/A	A) Human error in following procedures     B) Training inadequate     C) Inadequate personnel protective equipment	Requirements for a safety harness and lifeline (retrieval system as required by FERMCO evaluation)     Fall Protection Plan is approved prior to work     Fall protection training is completed prior to work	Standard Hazard

A-11 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators Co	Comment	
Hazard Type: 6 Hazard Description: Activities <sup>a</sup> Associate			6				
Possible serious personnel injury/death			N/A	A) Human error in following procedures     B) Training inadequate     C) Inadequate personnel protective equipment		endard ezard	
Hazard Type: 7 Hazard Description: Activities* Associate			9, 13, 1	4, 21d, 22, 62, 63			
Possible serious personnel injury/death				A) Shorts in electrical cables	1	andard szard	
Impact on site safety function Loss of power for				constr	B) Overhead lines in work area resulting in construction equipment accident     C) Underground line in area not known	Supervisor shall ensure proper review of all electrical interfaces prior to implementation     Construction Engineer shall ensure that Construction Environmental Health and Safety Work Survey was performed.	
production, schedule impact  Local fire			D) Lock and tag failures or procedures not followed     E) Training inadequate     F) Inadequate PPE	Supervisor shall ensure proper review of all electrical interfaces prior to implementation     Facility Owner shall ensure the proper implementation of energy control lock and tag procedure			
				G) Electrical fire	Design includes a process shutdown to safe condition upon electrical failure		

A-12 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 7 Hazard Description: Activities Associate			ibution F	ower		
Loss of electrically- operated equipment and instrumentation	Below Concern	Unlikely	0	A) Equipment failure	Design includes backup power for critical functions     Design includes redundant power supplies for critical systems     Facility Owner shall ensure routine preventive maintenance	
Equipment damage causing monetary loss				B) Human error	Supervisor shall ensure operators are trained and qualified on equipment operation and proper shutdown procedures	:
Possible personnel injury				C) Natural catastrophe	Design includes backup power for critical functions     Design includes redundant power supplies for critical systems	
Hazard Type: 8 Hazard Description: Activities* Associate				48, 49, 50, 52, 53, 60a		
Monetary loss due to equipment damage	Below Concern	Unlikely	0	A) Inadequate or failed freeze protection.	Design meets the cold protection provisions in DOE Order 6430.1A.	
Hazard Type: 8 Hazard Description: Activities Associate				, 22, 23, 24, 26, 26a, 51, 55, 59, 61, 63, 65, 66		
Equipment and structure damage  Burns or death to workers  Ignition of	Low	Unlikely	2	A) Insulation failure     B) Lack of insulation     C) Loss of cooling water	Design includes a fire protection system     Project procedures include a fire protection program     Hazardous Work Permits are issued to ensure PPE is used during work     Design includes temperature controls to idle or shut down the furnace     Furnace is surrounded by a metal cage to minimize contact	
combustible material nearby					with furnace.	

A-13 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 9 Hazard Description: Activities Associate				, 48, 50, 53, 54, 55, 56, 57, 58, 59, 60, 60a, 61, 6	54, 65	
Loss of primary air supply Loss of cooling			n/a	A) Weld/Seam Failure	Construction Engineer will ensure pre-operational testing.     Secondary Air Supply in place for critical functions.     Cooling water backup in place for critical functions.	Standard Hazard
water Loss of recycle water				B) Tank overpressurized	Pressure Relief Valve in place to relieve pressure in air system.     Supervisor will ensure successful completion of training and qualifications on system operation.     Cooling water backup in place for critical functions.	
Hazard Type: 10 Hazard Description: Activities* Associate				3, 34		
Possible serious personnel injury/death  Equipment damage/loss	Moderate	Unlikely	5	A) Rigging failure	Supervisor shall ensure proper use of the rigging plan     Supervisor shall ensure successful completion of training and qualification on heavy equipment use	WSS Structural Dome Limit has been established
Spread of airborne radioactive and hazardous contamination				B) Excessive loads on the dome cause collapse	Load limits on the dome have been established and are implemented in any activity requiring access to the silo domes	
Internal/external exposure					Uonica	
Loss of containment						

A-14 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment				
II '	lazard Type: 10  lazard Description: Hazardous Material Release from Day Tank  Activities' Associated with the Hazard: 64									
Environmental Release	Below Concern	Unlikely	0	A) Weld failure     B) Material defect						
Hazard Type: 10 Hazard Description: Activities* Associate				System) i, 37, 38, 39, 40, 49, 50						
Release of silo headspace gas recycle water, or furnace gas which contains radon  Possible personnel injury  Equipment damage causing monetary loss	Low	Unlikely	2	A) Weld or seam failure     B) Material defect	QA/QC Engineer will ensure inspection of all welds     Construction Engineer will ensure pre-operational testing     Supervisor will ensure successful completion of training and qualification on system operation					
Hazard Type: 10 Hazard Description: Activities* Associate			uilding)							
Release of radium- bearing residues and dust Potential internal exposure	Below Concern	Unlikely	0	A) Forklift accident with vitrified product	Supervisor shall ensure successful completion of training and qualification for forklift operators     Radiation work permit will ensure proper usage of PPE during forklift operations.					

A-15 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 10 Hazard Description: Activities Associate			Heavy	Metals from Furnace		
	Moderate	Unlikely	5	A) Loss of containment due to material defect     B) Loss of containment due to worker error during installation	Design includes containment for furnace melt     Construction Acceptance Testing (CAT) performed prior to furnace startup	WSS Lessons learned from the MAWS project incorporated
				C) Loss of containment due to worker error from lack of training on system operation	Successful completion of operator training and qualification on the vitrification system operation will occur prior to working with furnace     Design includes containment for furnace melt	
				D) Loss of containment due to fire in furnace area	Facility Owner shall ensure that the work area minimizes the storage of combustible materials in the vitrified area     Design includes containment for furnace melt	
Hazard Type: 10 Hazard Description: Activities Associate				ge bin, slurry tanks and transfer piping , 18, 19		
Personnel injury  Exposure to airborne radioactive and hazardous material to the public and workers	Low	Unlikely	2	A) Material defect     B) Weld failure or seam failure     C) Operator error     D) Forklift accident	Secondary containment for process vessels is used to contain the release of material from spreading to other areas     Procedures are in place to minimize the transfer of contamination to equipment prior to starting work     Successful completion of training and qualification on material handling and decontamination procedures will occur prior to starting work with radioactive material	

A-16 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 10 Hazard Description: Activities* Associate			2) Fails			
Release of slurry with K-65 residues causing spread of contamination	es F	Unlikely	2	A) Material defect     B) Weld or seam failure	Design includes use of double wall pipe in outdoor areas and an Leak Detection System     Construction Engineer shall ensure pre-operational testing of slurry line     QA/QC Engineer shall ensure inspection of all welds	
Possible personnel exposure				C) Slurry line overpressurized	Design includes overpressurization protection     Construction Engineer shall ensure pre-operational testing of slurry line	
Possible equipment damage				D) Freeze/thaw action on slurry line	1. Design includes freeze protection for the slurry line	
				E) Vehicle accident pulls slurry line from silo     F) Crane accident pulls slurry line from silo	Design locates the contaminated pipes in controlled areas     Supervisor shall ensure successful completion of training and qualification on vehicle operations, crane operation, and process operation for workers conducting those activities	
Hazard Type: 10 Hazard Description: Activities Associate			ressure /	Water Line		
	Below Concern	ow Concern Unlikely	0	A) Overpressurization of line	Design locates contaminated pipes in controlled areas     Design includes overpressure protection     Design includes double walled pipe where appropriate     Design includes a Leak Detection System     Supervisor shall ensure successful completion of training and qualification on system operation	
Equipment damage causing monetary loss	·			B) Weld or seam failure     C) Material defect	QA/QC Engineer shall ensure inspection of all welds     Construction Engineer shall ensure pre-operational testing     Design includes double walled pipe where appropriate     Design includes a Leak Detection System     Design locates contaminated pipes in controlled areas	

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Санѕе	Controls/Mitigators	Comment
Hazard Type: 11 Hazard Description: Activities Associate			ined spa	pe		
Possible serious personnel injury/death			N/A	A) Human error in following procedures     B) Training inadequate     C) Inadequate personnel protective equipment	Continuous air monitoring is required in confined spaces     Safety harness and lifeline     Fall protection requirements     Entrant/attendant confined space training for permit required confined spaces     FERMCO Confined Space Permit requirements     Requirement for standby person for confined space     Requirement for ventilation	Standard Hazard
Hazard Type: 12 Hazard Description: Activities* Associate			Related (	(Industrial)		
Possible serious personnel injury/death			N/A	A) Improper use of electrical supply, equipment, safety devices due to human error during construction     B) Equipment energized during installation/testing activities	Workers will receive general site worker training in addition to task specific training     Procedures are approved prior to work initiation	Standard Hazard
				C) Slip, trip and fall accidents D) Vehicle impact E) Eye injury F) Ear injury - excessive noise	Workers will receive general site worker training in addition to task-specific training	
				G) Material handling equipment is less-than- adequate	QA/QC Engineer shall ensure equipment inspection and testing prior to work initiation	
				H) Trench or excavation failure	Procedures for Excavation Penetration Permits and Facility     Outage Permits are issued     Construction Engineer shall ensure the proper use of trench boxes, shoring, sloping, etc.	

A-18 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 12 Hazard Description: Activities* Associate			6			
Possible serious personnel injury/death	nnel		N/A	A) Equipment failure     B) Lack of maintenance of lifting equipment	Project Engineer will ensure equipment maintenance was completed prior to initiation of work	Standard Hazard
Equipment						
failure/damage  Possible release of radioactive or hazardous contaminants	e/damage ble release of active or dous		C) Operator error due to inad D) Inadequate rigging design	C) Operator error due to inadequate training     D) Inadequate rigging design	Project Engineer shall ensure that the procedures are approved prior to work initiation     Completion of training and qualification on hoisting and rigging will occur prior to initiation of work     A complete sitewide hoisting and rigging plan (SSOP) is available prior to initiation of work	
Hazard Type: 13 Hazard Description Activities* Associate	d with the Hazard		6, 8, 11	, 21d, 21e, 21f, 22, 23, 24, 26, 27, 28, 29, 30, 31	, 32, 41, 42, 43, 45, 46, 47, 48, 49, 50, 51, 53, 54, 55, 56, 57	, 59,
Possible serious personnel injury			N/A	A) Human error in following procedures     B) Training inadequate     C) Inadequate personnel protective equipment	<ol> <li>Hearing protection is provided for employees exposed to ≥85 dBA 8 hr. TWA</li> <li>Medical monitoring is established for employees exposed to ≥85 dBA 8 hr. TWA</li> </ol>	Standard Hazard
Hazard Type: 13 Hazard Description: Activities Associate		: 1, 3, 4, 5, 6,	8, 11, 2	eld, 21e, 21f, 22, 23, 24, 26, 27, 42, 43, 51, 55, 5	8, 59, 61, 62, 63	
Personal injury			N/A	A) Elevated worker temperatures from working inadequate Personnel Protective Equipment (PPE)     B) Inadequate rest periods     C) Worker failure to recognize symptoms of heat distress	Hazardous Work Permits will establish rest periods, cooling appurtenances, and use of the buddy system	Standard Hazard

A-19 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 13 Hazard Description: Activities* Associate				29, 30, 31, 63, 64		
Personal Injury	Below Concern	Anticipated	0	A) Inadequate lighting design     B) Power failure     C) Lighting fixture failure	Emergency lighting is supplied where appropriate	Standard Hazard
Hazard Type: 15 Hazard Description: Activities* Associate				, Snakes, and Poison Ivy)		
Possible personnel illness/death			N/A	A) Inadequate personnel protective equipment	1. Construction Engineer shall ensure PPE is issued.	Standard Hazard
Hazard Type: 15 Hazard Description: Activities* Associate	•		oss of I	Power		
Molten glass would solidify in place possibly causing irreparable damage to the melter/furnace	Below Concern	Anticipated	0	A) Loss of electricity to the melter	Design includes insulation to maintain melt for approximately 8 hours.     Design includes bottom drain to empty furnace contents	
Adverse impact to project schedule						
Hazard Type: 15 Hazard Description: Activities' Associated			6, 16, 2	25		
Possible serious personnel injury/death			N/A	A) Poor traffic patterns used by operations     B) Operator error	Supervisor shall ensure successful completion of qualification training for vehicle operators     Task-specific procedures are approved prior to work initiation	Standard Hazard
Equipment damage					The project design restricts traffic in controlled areas     Facility Owner shall ensure that the project design includes necessary traffic barriers and controls	
radioactive or hazardous contaminants						

A-20 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 15 Hazard Description: Activities Associate	•	: 1, 2, 3, 4, 5,	6			
Unsafe operating conditions could result in possible personnel injury			N/A	A) Failure of management and union to agree     B) Improper industrial relations	Industrial Relations Representative shall ensure that formal industrial relations policies are followed     Trades Supervisor shall ensure that formal industrial relations policies are followed	Standard Hazard
Unsafe operating conditions could result in possible equipment damage						
Hazard Type: 15 Hazard Description: Activities Associate				3, 34	•	
None		Incredible	0	A) Aircraft crash	Not a credible scenario since the nearest airport is 4.7 miles away and not considered a reasonable concern. The probability of an airplane crash at the FEMP is less than 10 <sup>6</sup> .	
Hazard Type: 15 Hazard Description Activities Associate		: 9, 18, 19, 21	b, <b>24,</b> 3:	3, 34		
None		Incredible	0	A) Large Dam break or overflow	Not a credible scenario since there are no dams immediately upstream of facility.	
Hazard Type: 15 Hazard Description Activities' Associate						
None		Incredible	ő	A) Rail car accident/explosion	Not a credible scenario since no railroad tracks are in the immediate vicinity of facility.	
Hazard Type: 15 Hazard Description Activities Associate			b, 24, 3	3, 34		•
None		Incredible	0	A) Barge accident/explosion	Not a credible scenario since none in vicinity of facility.	

A-21 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment			
•	Hazard Type: 15 Hazard Description: External Event Activities* Associated with the Hazard: 9, 18, 19, 21b, 24, 33, 34								
			N/A	A) Sabotage	Excluded due to site security procedures per DOE Order 5480.23.				
Hazard Type: 15 Hazard Description: Activities* Associated			o, 24, 33	3, 34					
Reportable event to the contaminated worker or public Personnel injury or death	Low	Unlikely	2	A) EBA/DBA High Velocity Winds B) EBA/DBA Earthquake	Design has included building evacuation system     Design of new facilities to incorporate seismic and natural phenomena hazards as outlined in DOE Order 6430.1A, UCRL-15910, and DOE 5480.28				
Equipment damage									
Release of silo material									
Release of pilot plant material									

A-22 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment				
	Hazard Type: 15 Hazard Description: Severe Natural Phenomena Activities' Associated with the Hazard: 9, 18, 19, 21b, 24, 33, 34									
Reportable event to the contaminated worker or public	Low	Extremely Unlikely	1	A) Tornado     B) Beyond EBA/DBA High Velocity Winds     C) Beyond EBA/DBA Earthquake	1. Design has included building evacuation system					
Personnel injury or death										
Equipment damage										
Release of silo material										
Release of pilot plant material										
Hazard Type: 15 Hazard Description: Activities* Associate			o, <b>24</b> , 33	3,34	, <u> </u>					
Reportable event to the contaminated worker or public	Moderate	Incredible	0	A) Other facilities in area	Nearest facility (CRU1 Support Facility) is at least 200 meters away.					
Personnel injury or death										
Equipment damage										
Release of silo material										
Release of pilot plant material										

A-23 Rev. No.: 0

Consequence (Unmitigated)	Consequence Class	Frequency Class	Bin	Cause	Controls/Mitigators	Comment
Hazard Type: 15 Hazard Description: External fire Activities* Associated with the Hazard: 9, 18, 19, 21b, 24, 33, 34						
Reportable event to the contaminated worker or public  Personnel injury or death  Equipment damage  Release of silo material  Release of pilot plant material	Moderate	Extremely Unlikely	3	A) Combustible material stored near silos and pilot plant	Design has fire protection system     Nearest facility (CRU1 Support Facility) is at least 200 meters away	
* The activity numbers are defined in Table 5.						

A-24 Rev. No.: 0